
WATER SUPPLY PROJECT

CHAPAKHORI, KAVRE

(Nepal)

SITE VISIT REPORT

**HELP IN ACTION
HELP IN ACTION ONLUS**

VERSATILE WORKS ENGINEERING COMPANY
29/05/2022

1. INTRODUCTION

With the sole objective to acknowledge the present condition and to foresee commencement of work regarding local issues as well, the team of construction experts visited the site on 29th May, 2022.

2. VISIT ITINERARY

The days of activities are summarized in the table below:

Day	Date	Activities
1	29 May 2022 Sunday	0730 AM – Departed from Kathmandu. 1100 AM – Arrived Chapakhori. 0430 PM – Departed from Chapakhori. 0730 PM – Arrived Kathmandu.

3. SITE VISIT OBJECTIVES and ACTIVITIES

- Observation of the site.
- Observation of the access.
- Discussion, investigation, check and confirmation of the site issues.
- Correlation with the local representatives and helping workers.
- Availability of the materials.
- Seeking out the storage point for the delivery of materials.


4. SITE Photographs







5. GOOGLE IMAGE FOR PROPOSED NEW ALIGNMENT



6. CONCLUSION

- Site recce and confirmation on planning of work.
 - Discussed with local representatives regarding the skilled and unskilled labors.
 - Investigate the availability of construction materials.
 - Finding of better route for the pipe layout.
- It has been shown in the Google map image in clause 5, which shall be discussed.